

**Board of Trustees  
Barton Community College  
July 14, 2015 Board Meeting**

***Swimming Pool Ceiling Replacement***

**Detail:** Replace ceiling grid and tile – Due to the high humidity in the space and the age of the ceiling grid (1970), the ceiling grid and its supports have rusted and must be replaced. The ceiling grid supports the light fixtures, the ceiling tile, and the HVAC diffusers in the pool area. The pool must be drained, and the entire pool area will need to have scaffold set up in it to replace the grid. We have a 2 ½ week timeframe the beginning of August in which the pool is not being used.

Bid requests and specifications were sent out ceiling contractors. The results of the bids were as follows:

Sound Control – No bid

Midwest Acoustics – No bid

Amax Ceiling Contractors – No bid

MCS Ceiling Contractors – No bid

Acoustic Contracting - \$53,320

**Recommendation:** It is recommended that the Board accept the bid from Acoustic Contracting in the amount of \$53,320.